

From: "Davis, Mike" <MDavis@archcoal.com>
To: "Chris Hansen (E-mail)" <CHansen@archcoal.com>, "Craig Hilton (E-mail)" <CHilton@archcoal.com>, "Daron Haddock (E-mail)" <daronhaddock@utah.gov>, "Dave Darby (E-mail)" <davedarby@utah.gov>, "Jerriann Ernstsen (E-mail)" <jerriannernstsen@utah.gov>, "Ken May (E-mail)" <KMay@archcoal.com>, "Mark Bunnell (E-mail)" <MBunnell@archcoal.com>, "Pam Grubaugh-Littig (E-mail)" <Pamgrubaughlittig@utah.gov>, "Pete Hess (E-mail)" <petehess@utah.gov>, "Steve Fluke (E-mail)" <stevefluke@utah.gov>, "Susan White (E-mail)" <susanwhite@utah.gov>
Date: 11/10/03 2:32PM
Subject: East Fork Box Canyon Monitoring

Attached is a map showing the 3LPE longwall face location as of 11-10-03. This map along with an excel spread sheet of the monitoring sites and subsidence cracks will be updated each Monday for the previous week. The longwall face should be starting into the angle-of-draw of the stream channel and rock shelter this week. Our plan is to start monitoring today (weather permitting) in the east fork of box canyon. Chris Hansen and Erik Petersen planned to monitor flow and look for subsidence cracks today and I plan to monitor for cracks later in the week.

Mike

<<3LPE WEEKLY MONITORING PDF 11-10-03.pdf>>